DAMS CLASSIFIED AS UNSAFE

Arizona Department of Water Resources Office of Water Engineering Dam Safety

Friday, July 29, 2005

Friday, July 29, 2005

Page 1 of 4

Apache

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
01.14 River Reservoir #3	High	Springerville	12.00	04/13/2004	
					Embankment
01.29 Colter	High	Greer	6.50	01/09/2001	
					Embankment
					Emergency Spillway
					Outlet Works
Cochise					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
02.05 Amerind #8	High		0.00	06/22/2001	
					Embankment
Coconino					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
03.09 City	High	Williams	1.00	12/30/1980	
					EAP
					Embankment
					Emergency Spillway
					Outlet Works
03.43 Fredonia	High	Fredonia	1.00	12/02/1980	
					Embankment
					Emergency Spillway
					Foundation
03.58 Flagstaff Reservoir East	High	24 Residences Near Dam	0.05	09/26/2003	
					EAP
Graham					
Graham SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:

Friday, July 29, 2005

					EAP
					Embankment
					Emergency Spillway
					Foundation
					Outlet Works
05.09 Lebanon Reservoir #2 (Lower)	High	Safford	8.00	07/10/2001	
					Embankment
					Emergency Spillway
					Foundation
					Other
					Outlet Works
05.16 Graveyard Wash	High	Safford	2.00	02/17/1981	
					Emergency Spillway
05.18 Stockton Wash Retarding	High	Safford	2.00	12/30/1981	
					Emergency Spillway
05.19 Frye Creek Retarding	High	Thatcher	1.00	12/30/1981	- 0 iii
					Emergency Spillway
Maricopa					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
07.42Buckeye FRS #1	High	Buckeye	3.00		
					Embankment
07.69 Lake Bonita	High	Residential Structures Below Dam	0.10		
					Embankment
Navajo					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
09.07 Millett Swale	High	Taylor & Shumway	4.00	06/12/1980	
					Embankment
					Emergency Spillway
09.09 Lone Pine	High	Schoens Dam	6.50	12/18/1979	
					Embankment

Friday, July 29, 2005

Emergency Spillway

Foundation

09.13 Jaques High Show Low 4.00 04/01/1981

Emergency Spillway

Pinal

SID Dam Name	Hazard Clas	s Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
11.05 Magma Retarding	High	Coolidge	12.00	05/02/1977	
					Embankment
					Emergency Spillway
11.06 Florence Retarding	High	Florence	1.50	11/20/1984	
					Embankment
					Emergency Spillway

Yavapai

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
13.14 Granite Creek	High	Granite Dells	1.00	09/09/1980	
					Concrete
					Emergency Spillway
13.48 Wineglass Ranch	High		0.00	05/29/2003	
					EAP
					Emergency Spillway

Friday, July 29, 2005